


Connector Types



J Series connectors have one contact grounded to the shell

(example 60 AMP Plug Insert 3 Pole 4 Wire)



K Series connectors have no contacts grounded to the shell

(example 60 AMP Plug Insert 4 Pole 4 Wire)

Connectors Come Standard With Solder Contacts

60 AMP Pressure Contact shown



Set Screw



- **PR** on the end of the part number indicates Pressure contacts. Connectors require a screwdriver to tighten the wire to the contact. 30 AMP connectors include a solderless crimp terminal.

HILLCREST ENTERPRISES, INC.
11092 AIR PARK ROAD
ASHLAND, VIRGINIA 23005 USA

PHONE 804-798-8390 FAX 804-752-7830

info@pylenational.co