


Connector Types



J Series connectors have one contact grounded to the shell

(example 60 AMP Plug Insert 3 Pole 4 Wire)



K Series connectors have no contacts grounded to the shell

(example 60 AMP Plug Insert 4 Pole 4 Wire)

Connectors Come Standard With Solder Contacts

60 AMP Pressure
Contact shown



Set Screw



- **PR** on the end of the part number indicates Pressure contacts. Connectors require a screwdriver to tighten the wire to the contact. 30 AMP connectors include a solderless crimp terminal.

HILLCREST ENTERPRISES-CT, LLC
248 KENT ROAD
NEW MILFORD, CONNECTICUT 06776 USA

PHONE 804-798-8390 FAX 860-350-5411

info@pylenational.co